



March 30, 2011

Division of State Architect
1515 Clay Street, Suite 1201
Oakland, CA 94612

Attention: Dan Chu
Supervisor Close out Team

Subject: Piedmont Unified School District
Havens Elementary School
Rebuild of School
DSA File No.: 1-31
DSA App No.: 01-110205
Project Close-out

Dear Mr. Chu:

The above listed project was submitted for final close-out on December 23, 2010 (copy attached), received by DSA on December 24, 2010 (copy of receipt attached). On March 14, I submitted a request to the close out team for a status report. March 24th, I received an email from Rey Malig, stating that this project is "Active" (copy attached). I am not exactly sure what this means, other than yes DSA has it to close out.

"Our client is requesting an estimated date for DSA Close-out with certification or review comments."


Can you please kindly provide an estimated date and any additional information available?
Thank you."

Sincerely,

A handwritten signature in black ink, appearing to read 'Donna L. Foster'.

Donna L. Foster
Construction Close-out

CC: Jim Hackett, DSA Regional Manager
Constance Hubbard, Superintendent, Piedmont Unified School District
Sherman Koo, Project Manager
Mark Bello, AOR



TRANSMITTAL FORM

ATTENTION:	Yung Su/Close out Team	DATE:	12/23/10
COMPANY:	Division of the State Architect (DSA)	PROJECT NO:	P7605
ADDRESS:	1515 Clay Street, Suite 1201 Oakland, CA 94612	PHONE NO:	(510) 662-3101
SUBJECT:	Havens Elementary School – Rebuild DSA File No. 1-31 DSA App No. 01-110205		

We are sending you the following:

- | | | |
|---|---|---|
| <input type="checkbox"/> Plans | <input type="checkbox"/> Engagement Letter | <input type="checkbox"/> Calculation Packages |
| <input type="checkbox"/> Correspondence | <input type="checkbox"/> Authorization for Additional Service | <input type="checkbox"/> RFI / Submittals |
| <input type="checkbox"/> Blueprints | <input type="checkbox"/> Originals | <input checked="" type="checkbox"/> Other Close out Documents |

Via:

☐ Delivery ☐ U.S. Mail ☒ Overnight ☐ Fax _____ Total pages (incl. transmittal)

Copies	No.	
1	1	DSA Tracker Requirements
1	2	DSA 6 Contractor
1	3	DSA 6 IOR
1	4	DSA 6A/E
1	5	DSA 108 AOR
1	6	NOC
1	7	DSA 291, DSA 292 (18), Glulam
1	8	DSA Approved Change Order #8 & 4
1	9	DSA Tracker Sheet showing Approved Fire Sprinkler System
1	10	Copy of Engineered Fill DSA 293 for 01-110621 Filed Under Interim Housing for entire site.
	11	

The above enclosures are transmitted as checked below:

- | | | |
|---|---|---|
| <input type="checkbox"/> For approval | <input type="checkbox"/> For your use | <input type="checkbox"/> As requested |
| <input type="checkbox"/> For review and comment | <input checked="" type="checkbox"/> For review and approval | <input type="checkbox"/> For your information |
| <input type="checkbox"/> For your action | <input type="checkbox"/> Other _____ | |

REMARKS:

--

Responsible ATI Individual: Donna Foster Copy to: file

Department of
General Services
BUILDING GREEN · BUYING GREEN · WORKING GREEN

Documents Required List For Project Certification

Office ID:01

Application #: 110205

File #:1-31

Project Name: Haven Elementary School

Project Scope: Construction of 2-Classroom Buildings, 1-Administration Building

Contracts

Contract #	Name	DSA-102 Received Date	DSA-6 Date Signed	N.O.C Date Completed
1	Webcor Builders	07/31/2009	✓	✓

Design Professionals DSA-6 A/E

Design Professional	Name	Date Signed
Electrical Engineer	Kamal Mirchandani	✓
Architect	John Sinclair MARK BELLO	✓
Architect	Carl Groch	
Geotech Engineer	John Egan	
Structural Engineer	Arunabha Saha	✓
Mechanical Engineer	Steve Sang Ki Lee SCOTT WALLAND	✓

General Inspectors DSA-6

Type	Name	Date Signed
Project Inspector		✓

Testing and Special Inspection Verified Reports

Document	Name	Date Signed
Engineered Fill	done under interim housing - SEE ATTACHED COPY	✓
Batch Plant Inspection		✓
Glu-laminated Beams		✓
Field Welding		✓
Shop Fabrication		✓
High Strength Bolt Installation		✓
Shop Welding		✓
Masonry Construction		✓
Lab Verified Report		✓

Change Orders

Contract #	Change Order #	Status
1	8 APPROVED	Not Approved ✓
1	4 u	Not Approved ✓

Deferred Approvals

Item	Date Approved
Elevator Guide Rails and Support Bracket Anchorage	04/15/2010
Window Wall Systems or Storefronts with spans greater than 10 feet	04/12/2010
Automatic Fire Sprinkler Systems	3/9/10
Basketball Backstops	06/09/2010

Dates indicate the item or document has been accepted. A blank field indicates either a missing or rejected item or document. Explanations regarding the rejection of a received item or document can be found in the Notes section.

Only unapproved change orders appear on this page. To view all change orders go to DSA's web site at www.dsa.dgs.ca.gov

[Conditions of Use](#) | [Privacy Policy](#)
Copyright © 2007 State of California

CALIFORNIA DEPARTMENT OF GENERAL SERVICES
DIVISION OF THE STATE ARCHITECT



VERIFIED
REPORT

DSA-6
Rev 04/08

File this report at completion of project, when services in connection with the project are terminated, when work stops for more than one month, or when any building of the project is occupied. See instructions on page 2. Refer also to California Code of Regulations, Title 24, Part 1, Sections 4-214 (for essential services buildings) and 4-336 (for schools).

1.	<input checked="" type="checkbox"/> Final - All work complete (entire DSA approved scope is 100% complete)		3.	DSA File No. 1-31
2. Check all applicable boxes:	<input type="checkbox"/> Work not completed (describe in box 10 below) <input type="checkbox"/> Terminating <input type="checkbox"/> Occupied Building(s) _____ <input type="checkbox"/> Work Stopped		DSA Application No. 01 - 110205	
4. School District/Owner: Piedmont Unified School District			5. Project Name (School): Havens Elementary School	
6. Scope of Entire Project: Construction of 2 Classroom Buildings, 1 Admin Building				
7. Contract Number: _____		8. Final Project (or contract) Cost (Required only if work 100% complete) \$ 21,292,095.00		9. Total Project Completion (% complete for entire DSA approved scope): 100 %
10. Describe all non-compliant work and/or work to be completed: (<input type="checkbox"/> _____ additional pages attached):				

11. Total No. of change orders received: 10 Total No. of DSA approved change orders received: 10

12. I know of my own personal knowledge that all construction has, in every material respect, been performed in compliance with the DSA approved documents. I declare under penalty of perjury that I prepared this report and that all statements are true.

Signature: Kurt Forsgren Print Name: Kurt Forsgren Date: 12-21-10

Serving as: ☐ Project Inspector ☒ Contractor ☐ Other: _____

Business Address: 951 Mariners Island Boulevard, Suite 700

City: San Mateo State: CA Zip: 94404

13. Contractor must complete the following:

I am an authorized official of Webcor

working in the capacity of Sr. Project Manager

with personal knowledge of the work of construction. I have been authorized by said firm or corporation to sign this report.

Submit completed form to the DSA Regional Office where this project was filed:			
<input checked="" type="checkbox"/> DSA San Francisco Bay Area Region 1515 Clay Street, Suite 1201 Oakland, CA 94612	<input type="checkbox"/> DSA Sacramento Region 1102 Q Street, Suite 5200 Sacramento, CA 95811	<input type="checkbox"/> DSA Los Angeles Basin Region 700 N. Alameda Street, Suite 5-500 Los Angeles, CA 90012	<input type="checkbox"/> DSA San Diego Region 10920 Via Frontera Road, Ste 300 San Diego, CA 92127



DIVISION OF THE
STATE ARCHITECT



VERIFIED
REPORT

DSA-6
Rev 03/07

File this report at completion of project, when services in connection with the project are terminated, when work stops for more than one month, or when any building of the project is occupied. See instructions on page 2. Refer also to California Code of Regulations, Title 24, Part 1, Sections 4-214 (for essential services buildings) and 4-336 (for schools).

1. <input checked="" type="checkbox"/> Final - All work complete (entire DSA approved scope is 100% complete)	3. DSA File No. 1-31
2. Check all applicable boxes: <input type="checkbox"/> Work not completed (describe in box 10 below) <input type="checkbox"/> Terminating <input type="checkbox"/> Work Stopped <input checked="" type="checkbox"/> Occupied Building(s) All	DSA Application No. 01 - 110205
4. School District/Owner: Piedmont Unified School District	5. Project Name (School): Havens Elementary School
6. Scope of Entire Project: Campus Replacement	
7. Contract Number: All	8. Final Project (or contract) Cost (Required only if work 100% complete) \$ 21,292,095.00
9. Total Project Completion (% complete for entire DSA approved scope): 100 %	
10. Describe all non-compliant work and/or work to be completed: (<input type="checkbox"/> 0 additional pages attached):	

11. Total No. of change orders received: 10 Total No. of DSA approved change orders received: 10

12. I know of my own personal knowledge that all construction has, in every material respect, been performed in compliance with the DSA approved documents. I declare under penalty of perjury that I prepared this report and that all statements are true.

Signature: [Signature] Print Name: Jeff MacInnes Date: Dec 14, 2010

Serving as: ☒ Project Inspector ☐ Contractor ☐ Other:

Business Address: 3069 Alamo Drive, Suite 190

City: Vacaville State: CA Zip: 95687

13. Contractor must complete the following:

I am an authorized official of _____

working in the capacity of _____

with personal knowledge of the work of construction. I have been authorized by said firm or corporation to sign this report.

Submit completed form to the DSA Regional Office where this project was filed:

☒ DSA San Francisco Bay Area Region 1515 Clay Street, Suite 1201 Oakland, CA 94612
☐ DSA Sacramento Region 1102 Q Street, Suite 5200 Sacramento, CA 95811-6550
☐ DSA Los Angeles Basin Region 700 N. Alameda Street, Suite 5-500 Los Angeles, CA 90012
☐ DSA San Diego Region 16680 West Bernardo Drive San Diego, CA 92127





To be filled by the design professional in general responsible charge at completion of project, when services in connection with the project are terminated, when work stops for more than one month, or when any building of the project is occupied. See instruction on page 2. Refer also to California Code of Regulations, Title 24, Part 1, Section 4-214 (for essential services buildings) and 4-336 (for schools).

1.	<input checked="" type="checkbox"/> Final - All work complete (entire DSA approved scope is 100% complete)		3.	DSA File No. 1-31
2. Check all applicable boxes:	<input type="checkbox"/> Work not completed (describe in box 10 below) <input type="checkbox"/> Terminating <input type="checkbox"/> Occupied Building(s) <input type="checkbox"/> Work Stopped		DSA Application No. 01 - 110205	
4. School District/Owner: Piedmont Unified School District			5. Project Name (School): Havens Elementary School	
6. Scope of Entire Project: Construction of 2 Classroom Buildings, 1 Admin Building				
7. Final Project Cost: \$ 21,292,095.00 (Required only if work 100% complete)			8. This report includes all construction work through: Aug 5, 2010	
9. Total Project Completion (estimate total percentage of completion for projects where work is not complete): 100 %				
10. Describe all non-compliant work and/or work to be completed: (<input type="checkbox"/> additional pages attached):				

11. Total No. of change orders issued: 10 Total No. of DSA approved change orders issued: 10

12. AFFIDAVIT OF RESPONSIBLE PARTIES

I know of my own personal knowledge that all construction has, in every material respect, been performed in compliance with the DSA approved documents. I declare under penalty of perjury that I reviewed this report and that all statements are true.

Design Professional in general responsible charge for observation of all work

Signature: [Signature] Print Name: Mark Bello Date: 12-16-10
Address: 3860 Blackhawk Road City: Danville State: CA Zip: 94506

Structural Engineer delegated responsibility for observation of structural work

Signature: [Signature] Print Name: Arun Saha Date: 12/13/10
Address: 3860 Blackhawk Road City: Danville State: CA Zip: 94506

Mechanical Engineer delegated responsibility for observation of the mechanical and plumbing work

Signature: [Signature] Print Name: Scott Wayland Date: 12-13-10
Address: 3860 Blackhawk Road City: Danville State: CA Zip: 94506

Electrical Engineer delegated responsibility for observation of the electrical work

Signature: [Signature] Print Name: Kamal Mirchandani Date: 12/14/10
Address: 3860 Blackhawk Road City: Danville State: CA Zip: 94506

Submit completed form to the DSA Regional Office where this project was constructed:

- ☒ DSA San Francisco Bay Area Region 1515 Clay Street, Suite 1201 Oakland, CA 94612
 ☐ DSA Sacramento Region 1102 Q Street, Suite 5200 Sacramento, CA 95811
 ☐ DSA Los Angeles Basin Region 700 N. Alameda Street, Suite 5-500 Los Angeles, CA 90012
 ☐ DSA San Diego Region 10920 Via Frontera Road, Ste 300 San Diego, CA 92127



State of California • Arnold Schwarzeneger, Governor
State and Consumer Services Agency • Department of General Services
DIVISION OF THE STATE ARCHITECT
PLEASE SUBMIT THIS FORM TO YOUR LOCAL DSA REGIONAL OFFICE

FORM
DSA-108
Rev 4/08

CHANGE IN DELEGATION OF RESPONSIBILITY

Project Name: Havens ES Rebuild	Effective Date of Delegation: 12132010	File No. 1-31
		Application No. 01 - 110205

Acting for the school board/owner in the legal capacity of agent, I hereby request that the application for approval of drawings and specifications for the subject project be amended to delegate responsibility

for the ☐ preparation of plans and specifications

☒ observation of the construction

of the _____ portion of the construction (line # 22, of the application) as follows:

Delegated from: Carl Groch

☒ Architect ☐ Structural Engineer ☐ Mechanical Engineer ☐ Electrical Engineer ☐ Geotechnical Engineer

Delegated to: Mark Bello Registration #: C-20677 Phone #: (925) 648 - 8800

☒ Architect ☐ Structural Engineer ☐ Mechanical Engineer ☐ Electrical Engineer ☐ Geotechnical Engineer

Firm Name / Address: ATI Architects and Engineers
3860 Blackhawk Road
Danville, CA 94506

Responsibility Accepted by:

(*Original "wet" Signature of Architect or Engineer accepting responsibility)

12.16.10
Date:

Authorized Agent:

(*Original "wet" Signature of authorized agent)

Date:

NOTE

Persons delegated responsibility for observation of construction, or portions thereof, shall make verified reports (Form DSA-6A/E) to the Division of the State Architect (DSA), as required by Section 4-336, Part 1, Title 24, California Code of Regulations.

Persons relieved of responsibility for observation of construction, or portions thereof, shall make a verified report (Form DSA-6A/E) covering the work done up to the date their responsibility terminated.

* Whenever Original "wet" signature is called for, if digital signature is used, it must use Public Key Cryptography.
Refer to DSA Procedure 08-01 for details.

ATI

DEC 13 2010

RECORDED:

Recording Requested By:
And When Recorded Mail to:

RECEIVED



2010315845

10/28/2010 12:25 PM

OFFICIAL RECORDS OF ALAMEDA COUNTY
PATRICK O'CONNELL
RECORDING FEE: 0.00

Michael Brady, Assistant Superintendent
Piedmont Unified School District
760 Magnolia Avenue
Piedmont, CA 94611-4088



1 PG

* Notice government code 27355

NOTICE OF COMPLETION

Notice Pursuant to Civil Code section 3093, must be recorded within 10 days after completion

NOTICE IS HEREBY GIVEN THAT:

1. The undersigned is an owner or agent of an owner of the estate or interest stated below.
2. The name of the Owner is Piedmont Unified School District.
3. The address of the Owner is 760 Magnolia Avenue, Piedmont, CA 94611-4088.
4. The nature of the estate or interest is in fee.
5. A work of improvement on the property hereinafter described was completed on October 6, 2010.
6. The work done was Havens Elementary School Replacement Project (located on the Haven's Elementary School Campus) in the Piedmont Unified School District under DSA File No. 1-31, DSA Application No. 01-110205.
7. The contractor for such work of improvement was Webeor Builders, 207 King St., Ste. 300, San Francisco, CA 94107.
8. The property on which said work of improvement was completed in the County of Alameda, State of California. The street address or legal description of said property is 323 Highland Avenue, Piedmont, CA 94611.

Dated: 10/28/10

Michael Brady, Assistant Superintendent

VERIFICATION

I, the undersigned, say: I am Assistant Superintendent for the Piedmont Unified School District and the declarant of the foregoing notice of completion, I have read said Notice of Completion and know the contents thereof; the same is true of my own knowledge. I hereby declare under penalty of perjury that the foregoing is true and correct.

Executed on: 10/28, 2010, at Piedmont, California

Michael Brady, Assistant Superintendent



**CONSOLIDATED ENGINEERING
LABORATORIES**

October 28, 2010

File #1-31
Application #01-110205
LEA #54

Electronic Reporting

LABORATORY FINAL VERIFIED REPORT (LVR)

See the attached Laboratory Verified Report (LVR), Form DSA-291 for the following:

Havens Elementary School New Classrooms and Admin. Bldg.
1800 Oakland Avenue
Piedmont, CA
CEL #10-22955PW

Consolidated Engineering Laboratories (CEL) performed the following:

1. Reinforcing steel material I.D., sampling, testing.
2. Concrete sampling and testing.
3. Mortar sampling and testing.


Respectfully submitted,
CONSOLIDATED ENGINEERING LABORATORIES

REVIEWING ENGINEER: CHRIS N. KAVALARIS, R.C.E.

cc: Division of State Architect
ATI (E)
MCS, Inc. (E)

PUSDc/o Vila Construction (E)
Piedmont Unified School District (E)
Webcor (E)

All reports are submitted as the confidential property of clients. Publication of statements, conclusions or extracts is reserved pending our written approval.







STATE OF CALIFORNIA • DEPARTMENT OF GENERAL SERVICES
DIVISION OF THE STATE ARCHITECT

FORM
DSA-291
Rev. 01/16/09

Laboratory Verified Report (LVR)

Note: This form must be submitted by the DSA approved testing laboratory within 14 days of the conclusion of the testing program, or when work has stopped for more than one month, or if the services of the laboratory have been terminated for any reason.

A.	Re: New Classrooms & Admin. Bldg. (CEL #10-22955PW) <u>Project Name</u> Havens Elementary School <u>School Name</u> To: Piedmont Unified School District <u>School Dist.</u> E-Mail to: <u>Address</u> mbrady(piedmont.k12.ca.ua <u>Michael Brady</u> <u>Attention</u>	1-31 <u>DSA File #</u> 01-110205 <u>DSA App. #</u> <input checked="" type="checkbox"/> Final-Work 100% Complete <input type="checkbox"/> In-Progress: _____ % Complete <input type="checkbox"/> Terminating: _____ % Complete
	B. It is my professional opinion that all of the structural tests required by the Division of the State Architect (DSA) approved documents for the project identified in Section A were performed. Any tests of which I am aware that were not performed are listed on an attachment to this report. I am of the professional opinion that the tests were performed in accordance with the requirements of the DSA approved documents.	
C.	All reports were sent to all entities as required by Section 4-335 of Title 24, Part 1.	
D.	Qualified personnel under my direct supervision conducted all sampling, handling, and testing services.	
E.	The results of all tests indicate that the materials tested comply with the requirements of the DSA approved documents.	
F.	I declare under penalty of perjury that this report was prepared under my direct supervision, I know the contents thereof, and that all of the statements are true and correct. <div style="display: flex; justify-content: space-between;"><div><u>Signed</u>  ENGINEERING MANAGER</div><div></div><div><u>10/28/10</u> Date</div></div> <div><u>Print Name:</u> Chris N. Kavalaris (See Attachment) <u>Lab Name:</u> Consolidated Engineering Laboratories <u>DSA / LEA #</u> 54 <u>Address:</u> 2001 Crow Canyon Road, Suite 100 <u>City:</u> San Ramon <u>State:</u> CA <u>Zip:</u> 94583</div>	

cc: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____



**CONSOLIDATED ENGINEERING
LABORATORIES**

October 26, 2010

File #1-31
Application #01-110205
LEA #54

Electronic Reporting

**RE: Havens Elementary School
New Classrooms and Administration Building
1800 Oakland Avenue
Piedmont, CA
CEL #10-22955PW**

Please see the attached Special Inspection Verified Report(s) for the subject project.

Copies of the attached DSA-292 SIVR form(s) have been submitted to all parties indicated on the report distribution as noted below.

Sincerely,

CONSOLIDATED ENGINEERING LABORATORIES

cc. Division of State Architect
ATI (E)
MCS, Inc. (E)

PUSDc/o Vila Construction (E)
Piedmont Unified School District (E)
Webcor (E)

All reports are submitted as the confidential property of clients. Publication of statements, conclusions or extracts is reserved pending our written approval.




STATE OF CALIFORNIA • DEPARTMENT OF GENERAL SERVICES
DIVISION OF THE STATE ARCHITECT

FORM
DSA-292
rev. 01/16/09

Special Inspection Verified Report (SIVR)

Note: This form must be submitted by the Special Inspector within 14 days of the conclusion of work requiring special inspection, or when work has stopped for more than one month, or if the services of the Special Inspector have been terminated for any reason.

A.	Re: New Classrooms & Admin Bldg. (CEL #10-22955PW)	1-31
	Project Name Havens Elementary School	DSA File # 01-110205
	School Name To: Piedmont Unified School District	DSA App. #
	School Dist.	<input checked="" type="checkbox"/> Final-Work 100% Complete
	E-Mail to: Address pete@vilaconstruction.com	<input type="checkbox"/> In-Progress: _____ % Complete
	Pete Palmer	<input type="checkbox"/> Terminating: _____ % Complete
	Attention	
B.	I personally performed all construction inspections described in Section C. My inspections were performed in accordance with the requirements of the DSA approved documents.	
C.	My work included continuous inspection of construction in accordance with the "DSA approved" documents as follows (list all special inspections performed and/or specific portions of the construction which you personally inspected.): Proofload testing on 01/11/10.	
D.	All inspection reports were sent to all entities as required by code.	
E.	I know of my own personal knowledge that the work has, in every material respect, been performed in compliance with the "DSA approved" documents, <u>except as follows</u> (if no exceptions, indicate "No Exceptions"): NO EXCEPTIONS.	
F.	I declare under penalty of perjury that I prepared the above report and that all statements are true.	
	Signed 	10.26.10
	Special Inspector Signature	Date
	Print Name: Michael Walters	Certification Number
	Lab Name: Consolidated Engineering Laboratories	DSA / LEA # 54
	Address: 2001 Crow Canyon Road, Suite 100	
	City: San Ramon	State: CA Zip: 94583

cc: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____




STATE OF CALIFORNIA • DEPARTMENT OF GENERAL SERVICES
DIVISION OF THE STATE ARCHITECT

FORM
DSA-292
rev. 01/16/09

Special Inspection Verified Report (SIVR)

Note: This form must be submitted by the Special Inspector within 14 days of the conclusion of work requiring special inspection, or when work has stopped for more than one month, or if the services of the Special Inspector have been terminated for any reason.

A.	Re: New Classrooms & Admin. Bldg. (CEL #10-22955PW)	1-31
	Project Name Havens Elementary School	DSA File # 01-110205
	School Name To: Piedmont Unified School District	DSA App. #
	School Dist.	<input checked="" type="checkbox"/> Final-Work 100% Complete
	E-Mail to:	<input type="checkbox"/> In-Progress: ____ % Complete
	Address pete@vilaconstruction.com	<input type="checkbox"/> Terminating: ____ % Complete
	Pete Palmer	
	Attention	
B.	I personally performed all construction inspections described in Section C . My inspections were performed in accordance with the requirements of the DSA approved documents.	
C.	My work included continuous inspection of construction in accordance with the "DSA approved" documents as follows (list all special inspections performed and/or specific portions of the construction which you personally inspected.): Proofload testing on 04/09/10.	
D.	All inspection reports were sent to all entities as required by code.	
E.	I know of my own personal knowledge that the work has, in every material respect, been performed in compliance with the "DSA approved" documents, <u>except as follows</u> (if no exceptions, indicate "No Exceptions"): NO EXCEPTIONS.	
F.	I declare under penalty of perjury that I prepared the above report and that all statements are true.	
	Signed  Special Inspector Signature	Date <u>10/11/10</u> Certification Number
	Print Name: Chad Shibley	
	Lab Name: Consolidated Engineering Laboratories	DSA / LEA # 54
	Address: 2001 Crow Canyon Road, Suite 100	
	City: San Ramon	State: CA Zip: 94583

cc: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____




STATE OF CALIFORNIA • DEPARTMENT OF GENERAL SERVICES
DIVISION OF THE STATE ARCHITECT

FORM
DSA-292
rev. 01/16/09

Special Inspection Verified Report (SIVR)

Note: This form must be submitted by the Special Inspector within 14 days of the conclusion of work requiring special inspection, or when work has stopped for more than one month, or if the services of the Special Inspector have been terminated for any reason.

A.	Re: New Classrooms & Admin. Bldg. (CEL #10-22955PW) Project Name Havens Elementary School School Name To: Piedmont Unified School District School Dist. E-Mail to: Address pete@vilaconstruction.com Pete Palmer Attention	1-31 DSA File # 01-110205 DSA App. # <input checked="" type="checkbox"/> Final-Work 100% Complete <input type="checkbox"/> In-Progress: ____ % Complete <input type="checkbox"/> Terminating: ____ % Complete
	B. I personally performed all construction inspections described in Section C . My inspections were performed in accordance with the requirements of the DSA approved documents.	
C. My work included continuous inspection of construction in accordance with the "DSA approved" documents as follows (list all special inspections performed and/or specific portions of the construction which you personally inspected.): Field welding on 10/19/09.		
D. All inspection reports were sent to all entities as required by code.		
E. I know of my own personal knowledge that the work has, in every material respect, been performed in compliance with the "DSA approved" documents, <u>except as follows</u> (if no exceptions, indicate "No Exceptions"): NO EXCEPTIONS		
F. I declare under penalty of perjury that I prepared the above report and that all statements are true. <div><div> Signed Special Inspector Signature</div><div>John C Hornyak CWI #95051821 OC1 EXP. 6/1/2013 Date</div><div>10/4/16 Date</div><div>AWS/CWI #95051821 Certification Number</div></div> Print Name: John Hornyak Lab Name: Consolidated Engineering Laboratories Address: 2001 Crow Canyon Road, Suite 100 City: San Ramon State: CA Zip: 94583 DSA / LEA # 54		

cc: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____



STATE OF CALIFORNIA • DEPARTMENT OF GENERAL SERVICES
DIVISION OF THE STATE ARCHITECT

FORM
DSA-292
rev. 01/16/09

Special Inspection Verified Report (SIVR)

Note: This form must be submitted by the Special Inspector within 14 days of the conclusion of work requiring special inspection, or when work has stopped for more than one month, or if the services of the Special Inspector have been terminated for any reason.


A.	Re: <u>New Classrooms & Admin. Bldg. (CEL #10-22955PW)</u>	1-31
	Project Name <u>Havens Elementary School</u>	DSA File # <u>01-110205</u>
	School Name <u>To: Piedmont Unified School District</u>	DSA App. #
	School Dist.	<input checked="" type="checkbox"/> Final-Work 100% Complete
	E-Mail to: <u>pete@vilaconstruction.com</u>	<input type="checkbox"/> In-Progress: ____ % Complete
	Address	<input type="checkbox"/> Terminating: ____ % Complete
	<u>Pete Palmer</u>	
	Attention	
B.	I personally performed all construction inspections described in Section C . My inspections were performed in accordance with the requirements of the DSA approved documents.	
C.	My work included continuous inspection of construction in accordance with the "DSA approved" documents as follows (list all special inspections performed and/or specific portions of the construction which you personally inspected.): <u>Shop welding on 12/02/09; Field welding, high strength bolting and NDT (UT) on 03/24-26/10.</u>	
D.	All inspection reports were sent to all entities as required by code.	
E.	I know of my own personal knowledge that the work has, in every material respect, been performed in compliance with the "DSA approved" documents, <u>except as follows</u> (if no exceptions, indicate "No Exceptions"): <u>NO EXCEPTIONS.</u>	
F.	I declare under penalty of perjury that I prepared the above report and that all statements are true.	
	Signed <u><i>Heath Vester</i></u>	<u>10/14/10</u> AWS/CWI #02020631
	Special Inspector Signature	Date Certification Number
	Print Name: <u>Heath Vester</u>	
	Lab Name: <u>Consolidated Engineering Laboratories</u>	DSA / LEA # <u>54</u>
	Address: <u>2001 Crow Canyon Road, Suite 100</u>	
	City: <u>San Ramon</u>	State: <u>CA</u> Zip: <u>94583</u>

cc: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____



Special Inspection Verified Report (SIVR)

Note: This form must be submitted by the Special Inspector within 14 days of the conclusion of work requiring special inspection, or when work has stopped for more than one month, or if the services of the Special Inspector have been terminated for any reason.

A.	Re: New Classrooms & Admin. Bldg. (CEL #10-22955PW)	1-31
	Project Name Havens Elementary School	DSA File # 01-110205
	School Name To: Piedmont Unified School District	DSA App. #
	School Dist. E-Mail to:	<input checked="" type="checkbox"/> Final-Work 100% Complete
	Address pete@vilaconstruction.com	<input type="checkbox"/> In-Progress: _____ % Complete
	Pete Palmer	<input type="checkbox"/> Terminating: _____ % Complete
Attention		
B.	I personally performed all construction inspections described in Section C. My inspections were performed in accordance with the requirements of the DSA approved documents.	
C.	My work included continuous inspection of construction in accordance with the "DSA approved" documents as follows (list all special inspections performed and/or specific portions of the construction which you personally inspected.): Masonry on 06/09/10.	
D.	All inspection reports were sent to all entities as required by code.	
E.	I know of my own personal knowledge that the work has, in every material respect, been performed in compliance with the "DSA approved" documents, <u>except as follows</u> (if no exceptions, indicate "No Exceptions"): NO EXCEPTIONS	
F.	I declare under penalty of perjury that I prepared the above report and that all statements are true.	
	Signed 	DSA #5249
	Special Inspector Signature	Date Certification Number
	Print Name: Banshi Kaul	
	Lab Name: Consolidated Engineering Laboratories	DSA / LEA # 54
	Address: 2001 Crow Canyon Road, Suite 100	
	City: San Ramon	State: CA Zip: 94583

cc: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____

**Special Inspection Verified Report (SIVR)**

Note: This form must be submitted by the Special Inspector within 14 days of the conclusion of work requiring special inspection, or when work has stopped for more than one month, or if the services of the Special Inspector have been terminated for any reason.

A.	Re: New Classrooms & Admin. Bldg. (CEL #10-22955PW)	1-31
	Project Name Havens Elementary School	DSA File # 01-110205
	School Name To: Piedmont Unified School District	DSA App. #
	School Dist. E-Mail to:	<input checked="" type="checkbox"/> Final-Work 100% Complete
	Address pete@vilaconstruction.com	<input type="checkbox"/> In-Progress: ____ % Complete
	Pete Palmer	<input type="checkbox"/> Terminating: ____ % Complete
	Attention	
B.	I personally performed all construction inspections described in Section C . My inspections were performed in accordance with the requirements of the DSA approved documents.	
C.	My work included continuous inspection of construction in accordance with the "DSA approved" documents as follows (list all special inspections performed and/or specific portions of the construction which you personally inspected.): Field welding and NDT (UT) on 03/23/10.	
D.	All inspection reports were sent to all entities as required by code.	
E.	I know of my own personal knowledge that the work has, in every material respect, been performed in compliance with the "DSA approved" documents, <u>except as follows</u> (if no exceptions, indicate "No Exceptions"): NO EXCEPTIONS.	
F.	I declare under penalty of perjury that I prepared the above report and that all statements are true.	
	Signed <u>Russell Sharp</u> Special Inspector Signature	Date <u>9/18/10</u> AWS/CWI #04020171 Certification Number
	Print Name: <u>Russell Sharp</u>	
	Lab Name: <u>Consolidated Engineering Laboratories</u>	DSA / LEA # <u>54</u>
	Address: <u>2001 Crow Canyon Road, Suite 100</u>	
	City: <u>San Ramon</u>	State: <u>CA</u> Zip: <u>94583</u>

cc: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____

**Special Inspection Verified Report (SIVR)**

Note: This form must be submitted by the Special Inspector within 14 days of the conclusion of work requiring special inspection, or when work has stopped for more than one month, or if the services of the Special Inspector have been terminated for any reason.


A.	Re: New Classrooms & Admin. Bldg. (CEL #10-22955PW)	1-31
	Project Name Havens Elementary School	DSA File # 01-110205
To: Piedmont Unified School District	School Name	DSA App. #
	School Dist.	<input checked="" type="checkbox"/> Final-Work 100% Complete
E-Mail to:	Address pete@vilaconstruction.com	<input type="checkbox"/> In-Progress: ____ % Complete
Pete Palmer	Attention	<input type="checkbox"/> Terminating: ____ % Complete
B.	I personally performed all construction inspections described in Section C . My inspections were performed in accordance with the requirements of the DSA approved documents.	
C.	My work included continuous inspection of construction in accordance with the "DSA approved" documents as follows (list all special inspections performed and/or specific portions of the construction which you personally inspected.): Field welding on 11/09/09.	
D.	All inspection reports were sent to all entities as required by code.	
E.	I know of my own personal knowledge that the work has, in every material respect, been performed in compliance with the "DSA approved" documents, <u>except as follows</u> (if no exceptions, indicate "No Exceptions"): NO EXCEPTIONS.	
F.	I declare under penalty of perjury that I prepared the above report and that all statements are true.	
	Signed <u>Sandra L Rodriguez</u>	<u>9-21-10</u> <u>AWS/CWI #09020741</u>
	Special Inspector Signature	Date Certification Number
	Print Name: <u>Sandra Rodriguez</u>	
	Lab Name: <u>Consolidated Engineering Laboratories</u>	DSA / LEA # <u>54</u>
	Address: <u>2001 Crow Canyon Road, Suite 100</u>	
	City: <u>San Ramon</u>	State: <u>CA</u> Zip: <u>94583</u>

CC: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____



Special Inspection Verified Report (SIVR)

Note: This form must be submitted by the Special Inspector within 14 days of the conclusion of work requiring special inspection, or when work has stopped for more than one month, or if the services of the Special Inspector have been terminated for any reason.

A.	Re: New Classrooms & Admin. Bldg. (CEL #10-22955PW)	1-31
	Project Name Havens Elementary School	DSA File # 01-110205
	School Name To: Piedmont Unified School District	DSA App. #
	School Dist. E-Mail to:	<input checked="" type="checkbox"/> Final-Work 100% Complete
	Address pete@vilaconstruction.com	<input type="checkbox"/> In-Progress: ____ % Complete
	Pete Palmer	<input type="checkbox"/> Terminating: ____ % Complete
	Attention	
B.	I personally performed all construction inspections described in Section C. My inspections were performed in accordance with the requirements of the DSA approved documents.	
C.	My work included continuous inspection of construction in accordance with the "DSA approved" documents as follows (list all special inspections performed and/or specific portions of the construction which you personally inspected.): Batch plant on 10/22/09.	
D.	All inspection reports were sent to all entities as required by code.	
E.	I know of my own personal knowledge that the work has, in every material respect, been performed in compliance with the "DSA approved" documents, <u>except as follows</u> (if no exceptions, indicate "No Exceptions"): NO EXCEPTIONS	
F.	I declare under penalty of perjury that I prepared the above report and that all statements are true.	
	Signed 	9-20-10 1050242
	Special Inspector Signature	Date Certification Number
	Print Name: John Marshall	
	Lab Name: Consolidated Engineering Laboratories	DSA / LEA # 54
	Address: 2001 Crow Canyon Road, Suite 100	
	City: San Ramon	State: CA Zip: 94583

cc: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____





STATE OF CALIFORNIA • DEPARTMENT OF GENERAL SERVICES
DIVISION OF THE STATE ARCHITECT

FORM
DSA-292
rev. 01/16/09

Special Inspection Verified Report (SIVR)

Note: This form must be submitted by the Special Inspector within 14 days of the conclusion of work requiring special inspection, or when work has stopped for more than one month, or if the services of the Special Inspector have been terminated for any reason.

A.	Re: New Classrooms & Admin. Bldg. (CEL #10-22955PW)	1-31
	Project Name Havens Elementary School	DSA File # 01-110205
	School Name To: Piedmont Unified School District	DSA App. #
	School Dist. E-Mail to:	<input checked="" type="checkbox"/> Final-Work 100% Complete
	Address pete@vilaconstruction.com	<input type="checkbox"/> In-Progress: _____ % Complete
	Pete Palmer	<input type="checkbox"/> Terminating: _____ % Complete
	Attention	
B.	I personally performed all construction inspections described in Section C. My inspections were performed in accordance with the requirements of the DSA approved documents.	
C.	My work included continuous inspection of construction in accordance with the "DSA approved" documents as follows (list all special inspections performed and/or specific portions of the construction which you personally inspected.): Shop welding on 06/10/10.	
D.	All inspection reports were sent to all entities as required by code.	
E.	I know of my own personal knowledge that the work has, in every material respect, been performed in compliance with the "DSA approved" documents, <u>except as follows</u> (if no exceptions, indicate "No Exceptions"): NO EXCEPTIONS	
F.	I declare under penalty of perjury that I prepared the above report and that all statements are true.	
	Signed  Special Inspector Signature	Date <u>9-22-2010</u> AWS/CWI #00080431
	Print Name: Dean Fonceca	Certification Number  Dean D Fonceca CWI 00080431
	Lab Name: Consolidated Engineering Laboratories	DSA / LEA # 54
	Address: 2001 Crow Canyon Road, Suite 100	
	City: San Ramon	State: CA Zip: 94583

CC: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____




STATE OF CALIFORNIA • DEPARTMENT OF GENERAL SERVICES
DIVISION OF THE STATE ARCHITECT

FORM
DSA-292
rev. 01/16/09

Special Inspection Verified Report (SIVR)

Note: This form must be submitted by the Special Inspector within 14 days of the conclusion of work requiring special inspection, or when work has stopped for more than one month, or if the services of the Special Inspector have been terminated for any reason.



A.	Re: New Classrooms & Admin. Bldg. (CEL #10-22955PW) Project Name Havens Elementary School School Name To: Piedmont Unified School District School Dist. E-Mail to: Address pete@vilaconstruction.com Pete Palmer Attention	1-31 DSA File # 01-110205 DSA App. # <input checked="" type="checkbox"/> Final-Work 100% Complete <input type="checkbox"/> In-Progress: _____ % Complete <input type="checkbox"/> Terminating: _____ % Complete
B.	I personally performed all construction inspections described in Section C . My inspections were performed in accordance with the requirements of the DSA approved documents.	
C.	My work included continuous inspection of construction in accordance with the "DSA approved" documents as follows (list all special inspections performed and/or specific portions of the construction which you personally inspected.): Field welding on 11/11/09, 11/24/09 and 12/04/09.	
D.	All inspection reports were sent to all entities as required by code.	
E.	I know of my own personal knowledge that the work has, in every material respect, been performed in compliance with the "DSA approved" documents, <u>except as follows</u> (if no exceptions, indicate "No Exceptions"): NO EXCEPTIONS	
F.	I declare under penalty of perjury that I prepared the above report and that all statements are true. Signed  Special Inspector Signature Date 20 Sep 10 AWS/CWI #08120211 Certification Number Print Name: Mark Heilmann Lab Name: Consolidated Engineering Laboratories DSA / LEA # 54 Address: 2001 Crow Canyon Road, Suite 100 City: San Ramon State: CA Zip: 94583	

cc: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____



Special Inspection Verified Report (SIVR)

Note: This form must be submitted by the Special Inspector within 14 days of the conclusion of work requiring special inspection, or when work has stopped for more than one month, or if the services of the Special Inspector have been terminated for any reason.

A.	Re: New Classrooms & Admin. Bldg. (CEL #10-22955PW)	1-31
	Project Name Havens Elementary School	DSA File # 01-110205
	School Name To: Piedmont Unified School District	DSA App. #
	School Dist. E-Mail to:	<input checked="" type="checkbox"/> Final-Work 100% Complete
	Address pete@vilaconstruction.com	<input type="checkbox"/> In-Progress: ____ % Complete
	Pete Palmer	<input type="checkbox"/> Terminating: ____ % Complete
	Attention	
B.	I personally performed all construction inspections described in Section C. My inspections were performed in accordance with the requirements of the DSA approved documents.	
C.	My work included continuous inspection of construction in accordance with the "DSA approved" documents as follows (list all special inspections performed and/or specific portions of the construction which you personally inspected.): Field welding, including NDT (UT), on 03/29/10.	
D.	All inspection reports were sent to all entities as required by code.	
E.	I know of my own personal knowledge that the work has, in every material respect, been performed in compliance with the "DSA approved" documents, <u>except as follows</u> (if no exceptions, indicate "No Exceptions"): NO EXCEPTIONS	
F.	I declare under penalty of perjury that I prepared the above report and that all statements are true.	
	Signed  Special Inspector Signature	Date <u>9-1</u>
	Print Name: Don Murphy	AWS/CWI #07020111
	Lab Name: Consolidated Engineering Laboratories	 Certification Number Don E. Murphy CWI 07020111 QC1 EXP. 2/1/2013
	Address: 2001 Crow Canyon Road, Suite 100	DSA / LEA # 54
	City: San Ramon	State: CA Zip: 94583

cc: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____




STATE OF CALIFORNIA • DEPARTMENT OF GENERAL SERVICES
DIVISION OF THE STATE ARCHITECT

FORM
DSA-292
rev. 01/16/09

Special Inspection Verified Report (SIVR)

Note: This form must be submitted by the Special Inspector within 14 days of the conclusion of work requiring special inspection, or when work has stopped for more than one month, or if the services of the Special Inspector have been terminated for any reason.


A.	Re: New Classrooms & Admin. Bldg. (CEL #10-22955PW)	1-31
	Project Name Havens Elementary School	DSA File # 01-110205
	School Name To: Piedmont Unified School District	DSA App. #
	School Dist. E-Mail to: Address pete@vilaconstruction.com	<input checked="" type="checkbox"/> Final-Work 100% Complete <input type="checkbox"/> In-Progress: _____ % Complete <input type="checkbox"/> Terminating: _____ % Complete
	Pete Palmer Attention	
B.	I personally performed all construction inspections described in Section C. My inspections were performed in accordance with the requirements of the DSA approved documents.	
C.	My work included continuous inspection of construction in accordance with the "DSA approved" documents as follows (list all special inspections performed and/or specific portions of the construction which you personally inspected.): Batch plant on 08/01, 05/09.	
D.	All inspection reports were sent to all entities as required by code.	
E.	I know of my own personal knowledge that the work has, in every material respect, been performed in compliance with the "DSA approved" documents, <u>except as follows</u> (if no exceptions, indicate "No Exceptions"): NO EXCEPTIONS	
F.	I declare under penalty of perjury that I prepared the above report and that all statements are true.	
	Signed 	Date _____ Certification Number _____
	Special Inspector Signature	
	Print Name: Dennis Bartlett	
	Lab Name: Consolidated Engineering Laboratories	DSA / LEA # 54
	Address: 2001 Crow Canyon Road, Suite 100	
	City: San Ramon	State: CA Zip: 94583

cc: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____



Special Inspection Verified Report (SIVR)

Note: This form must be submitted by the Special Inspector within 14 days of the conclusion of work requiring special inspection, or when work has stopped for more than one month, or if the services of the Special Inspector have been terminated for any reason.

A.	Re: New Classrooms & Admin. Bldg. (CEL #10-22955PW)	1-31
	Project Name Havens Elementary School	DSA File # 01-110205
	School Name To: Piedmont Unified School District	DSA App. #
	School Dist. E-Mail to:	<input checked="" type="checkbox"/> Final-Work 100% Complete
	Address pete@vilaconstruction.com	<input type="checkbox"/> In-Progress: ____ % Complete
	Pete Palmer	<input type="checkbox"/> Terminating: ____ % Complete
	Attention	
B.	I personally performed all construction inspections described in Section C . My inspections were performed in accordance with the requirements of the DSA approved documents.	
C.	My work included continuous inspection of construction in accordance with the "DSA approved" documents as follows (list all special inspections performed and/or specific portions of the construction which you personally inspected.): Shop welding on 08/13/09.	
D.	All inspection reports were sent to all entities as required by code.	
E.	I know of my own personal knowledge that the work has, in every material respect, been performed in compliance with the "DSA approved" documents, <u>except as follows</u> (if no exceptions, indicate "No Exceptions"): NO EXCEPTIONS	
F.	I declare under penalty of perjury that I prepared the above report and that all statements are true.	
	Signed  Special Inspector Signature	9/26/10 Date
	Print Name: Joe Kraft	AWS/CWI #09020871 Certification Number
	Lab Name: Consolidated Engineering Laboratories	DSA / LEA # 54
	Address: 2001 Crow Canyon Road, Suite 100	
	City: San Ramon	State: CA Zip: 94583

cc: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____




STATE OF CALIFORNIA • DEPARTMENT OF GENERAL SERVICES
DIVISION OF THE STATE ARCHITECT

FORM
DSA-292
rev. 01/16/09

Special Inspection Verified Report (SIVR)

Note: This form must be submitted by the Special Inspector within 14 days of the conclusion of work requiring special inspection, or when work has stopped for more than one month, or if the services of the Special Inspector have been terminated for any reason.

A.	Re: New Classrooms & Admin. Bldg. (CEL #10-22955PW)	1-31
	Project Name Havens Elementary School	DSA File # 01-110205
	School Name To: Piedmont Unified School District	DSA App. #
	School Dist. E-Mail to:	<input checked="" type="checkbox"/> Final-Work 100% Complete
	Address pete@vilaconstruction.com	<input type="checkbox"/> In-Progress: ____ % Complete
	Pete Palmer	<input type="checkbox"/> Terminating: ____ % Complete
	Attention	
B.	I personally performed all construction inspections described in Section C. My inspections were performed in accordance with the requirements of the DSA approved documents.	
C.	My work included continuous inspection of construction in accordance with the "DSA approved" documents as follows (list all special inspections performed and/or specific portions of the construction which you personally inspected.): Proofload testing on 01/06/10.	
D.	All inspection reports were sent to all entities as required by code.	
E.	I know of my own personal knowledge that the work has, in every material respect, been performed in compliance with the "DSA approved" documents, <u>except as follows</u> (if no exceptions, indicate "No Exceptions"): NO EXCEPTIONS	
F.	I declare under penalty of perjury that I prepared the above report and that all statements are true.	
	Signed  Special Inspector Signature	9-19-2010 Date
	Print Name: Art Lozano	Certification Number
	Lab Name: Consolidated Engineering Laboratories	DSA / LEA # 54
	Address: 2001 Crow Canyon Road, Suite 100	
	City: San Ramon	State: CA Zip: 94583

cc: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____

**Special Inspection Verified Report (SIVR)**

Note: This form must be submitted by the Special Inspector within 14 days of the conclusion of work requiring special inspection, or when work has stopped for more than one month, or if the services of the Special Inspector have been terminated for any reason.

A.	Re: New Classrooms & Admin. Bldg. (CEL #10-22955PW) Project Name Havens Elementary School School Name To: Piedmont Unified School District School Dist. E-Mail to: Address pete@vilaconstruction.com Pete Palmer Attention	1-31 DSA File # 01-110205 DSA App. # <input checked="" type="checkbox"/> Final-Work 100% Complete <input type="checkbox"/> In-Progress: _____ % Complete <input type="checkbox"/> Terminating: _____ % Complete
B.	I personally performed all construction inspections described in Section C . My inspections were performed in accordance with the requirements of the DSA approved documents.	
C.	My work included continuous inspection of construction in accordance with the "DSA approved" documents as follows (list all special inspections performed and/or specific portions of the construction which you personally inspected.): _____ Batch plant on 10/12/09.	
D.	All inspection reports were sent to all entities as required by code.	
E.	I know of my own personal knowledge that the work has, in every material respect, been performed in compliance with the "DSA approved" documents, <u>except as follows</u> (if no exceptions, indicate "No Exceptions"): _____ NO EXCEPTIONS	
F.	I declare under penalty of perjury that I prepared the above report and that all statements are true. Signed <u>James D. Currier</u> Special Inspector Signature <u>7-19-2010</u> Date <u>5040671-48</u> Certification Number Print Name: Jim Currier Lab Name: Consolidated Engineering Laboratories DSA / LEA # 54 Address: 2001 Crow Canyon Road, Suite 100 City: San Ramon State: CA Zip: 94583	

CC: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____

**DIVISION OF THE STATE ARCHITECT**



FORM

DSA-292

rev. 01/16/09

Special Inspection Verified Report (SIVR)

Note: This form must be submitted by the Special Inspector within 14 days of the conclusion of work requiring special inspection, or when work has stopped for more than one month, or if the services of the Special Inspector have been terminated for any reason.

A.	Re: New Classrooms & Admin. Bldg. (CEL #10-22955PW)	1-31
	Project Name Havens Elementary School	DSA File # 01-110205
	School Name To: Piedmont Unified School District	DSA App. #
	School Dist. E-Mail to: Address pete@vilaconstruction.com	<input checked="" type="checkbox"/> Final-Work 100% Complete <input type="checkbox"/> In-Progress: _____ % Complete <input type="checkbox"/> Terminating: _____ % Complete
	Pete Palmer Attention	
B.	I personally performed all construction inspections described in Section C . My inspections were performed in accordance with the requirements of the DSA approved documents.	
C.	My work included continuous inspection of construction in accordance with the "DSA approved" documents as follows (list all special inspections performed and/or specific portions of the construction which you personally inspected.): <u>Material I.D. on 09/08/09; shop welding, including NDT (UT/MT) on 09/14-18/09 and 09/21-25/09.</u>	
D.	All inspection reports were sent to all entities as required by code.	
E.	I know of my own personal knowledge that the work has, in every material respect, been performed in compliance with the "DSA approved" documents, <u>except as follows</u> (if no exceptions, indicate "No Exceptions"); <u>NO EXCEPTIONS.</u>	
F.	I declare under penalty of perjury that I prepared the above report and that all statements are true.	
	Signed  Special Inspector Signature	 <u>8-19-10</u> Date AWS/CWI #02050251 Certification Number
	Print Name: <u>Dennis Teal</u>	DSA / LEA # <u>54</u>
	Lab Name: <u>Consolidated Engineering Laboratories</u>	
	Address: <u>2001 Crow Canyon Road, Suite 100</u>	
	City: <u>San Ramon</u>	State: <u>CA</u> Zip: <u>94583</u>

cc: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____



STATE OF CALIFORNIA • DEPARTMENT OF GENERAL SERVICES
DIVISION OF THE STATE ARCHITECT

FORM
DSA-292
rev. 01/16/09

Special Inspection Verified Report (SIVR)

Note: This form must be submitted by the Special Inspector within 14 days of the conclusion of work requiring special inspection, or when work has stopped for more than one month, or if the services of the Special Inspector have been terminated for any reason.

A.	Re: New Classrooms & Admin. Bldg. (CEL #10-22955PW)	1-31
	Project Name Havens Elementary School	DSA File # 01-110205
To:	School Name Piedmont Unified School District	DSA App. #
	School Dist. E-Mail to: Address pete@vilaconstruction.com	<input checked="" type="checkbox"/> Final-Work 100% Complete <input type="checkbox"/> In-Progress: ____ % Complete <input type="checkbox"/> Terminating: ____ % Complete
	Pete Palmer Attention	
B.	I personally performed all construction inspections described in Section C. My inspections were performed in accordance with the requirements of the DSA approved documents.	
C.	My work included continuous inspection of construction in accordance with the "DSA approved" documents as follows (list all special inspections performed and/or specific portions of the construction which you personally inspected.): Field welding on 11/17/09, 05/10/10; Proofload (torque) testing on 05/10/10.	
D.	All inspection reports were sent to all entities as required by code.	
E.	I know of my own personal knowledge that the work has, in every material respect, been performed in compliance with the "DSA approved" documents, <u>except as follows</u> (if no exceptions, indicate "No Exceptions"): NO EXCEPTIONS	
F.	I declare under penalty of perjury that I prepared the above report and that all statements are true. Signed <u>Ken Pattee</u> <u>9-18-10</u> AWS/CWI #03070751 Special Inspector Signature Date Certification Number Print Name: <u>Ken Pattee</u> Lab Name: <u>Consolidated Engineering Laboratories</u> DSA / LEA # <u>54</u> Address: <u>2001 Crow Canyon Road, Suite 100</u> City: <u>San Ramon</u> State: <u>CA</u> Zip: <u>94583</u>	

cc: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____

**Special Inspection Verified Report (SIVR)**

Note: This form must be submitted by the Special Inspector within 14 days of the conclusion of work requiring special inspection, or when work has stopped for more than one month, or if the services of the Special Inspector have been terminated for any reason.

A.	Re: New Classrooms & Admin. Bldg. (CEL #10-22955PW) Project Name Havens Elementary School School Name To: Piedmont Unified School District School Dist. E-Mail to: Address pete@vilaconstruction.com Pete Palmer Attention	1-31 DSA File # 01-110205 DSA App. # <input checked="" type="checkbox"/> Final-Work 100% Complete <input type="checkbox"/> In-Progress: _____ % Complete <input type="checkbox"/> Terminating: _____ % Complete
B.	I personally performed all construction inspections described in Section C. My inspections were performed in accordance with the requirements of the DSA approved documents.	
C.	My work included continuous inspection of construction in accordance with the "DSA approved" documents as follows (list all special inspections performed and/or specific portions of the construction which you personally inspected.): Masonry on 07/12/10.	
D.	All inspection reports were sent to all entities as required by code.	
E.	I know of my own personal knowledge that the work has, in every material respect, been performed in compliance with the "DSA approved" documents, <u>except as follows</u> (if no exceptions, indicate "No Exceptions"): NO EXCEPTIONS	
F.	I declare under penalty of perjury that I prepared the above report and that all statements are true. Signed <u>Jeremy W Meade</u> 9.17.10 DSA #5311 Special Inspector Signature Date Certification Number Print Name: Jeremy Meade Lab Name: Consolidated Engineering Laboratories DSA / LEA # 54 Address: 2001 Crow Canyon Road, Suite 100 City: San Ramon State: CA Zip: 94583	

cc: Project Architect _____
Structural Engineer _____
Project Inspector _____
DSA Regional office _____



CONSOLIDATED ENGINEERING
LABORATORIES

November 19, 2009

File #1-31
Application #01-110205
LEA #54

Electronic Reporting

**RE: Havens Elementary School
New Classrooms and Admin. Bldg.
1800 Oakland Avenue
Piedmont, CA
CEL #10/22955PW**

**Inspection Date: 11/03/09
Location: Western Structures
Inspector: Forest Products Inspection, Inc.
Report #015**

GLUE LAMINATED MEMBER INSPECTION REPORT

On the above date, at our request, Forest Products Inspection performed inspections for the above referenced project.

Inspected glulam beam fabrication. Please refer to the attached for details of inspections performed.

REVIEWING ENGINEER: CHRIS N. KAVALARIS, R.C.E.

cc: Division of State Architect
ATI (E)
MCS, Inc. (E)

PUSDe/o Vila Construction (E)
Piedmont Unified School District (E)
Webcor (E)



Enclosures (2)

All reports are submitted as the confidential property of clients. Publication of statements, conclusions or extracts is reserved pending our written approval



FOREST PRODUCTS INSPECTION INC.

9739 Soda Bay Road, Kelseyville, CA 95451
Phone (707) 277-7778 Fax (707) 277-7779
Email fpiwood@mchsi.com

CERTIFICATE OF CONTINUOUS INSPECTION OF GLUE LAMINATED MEMBERS

Date:	11/3/2009	Job Code:	20099213.02
Project:	Havens Elementary School (Glulam Add #1), Piedmont, CA	DSA Application No.:	01-110205
Representative:	Consolidated Engineering Laboratories, Inc., San Ramon, CA	DSA File No.:	1 - 31
Manufacturer:	Western Structures, Eugene, OR	Representative No.:	10-22955PW
Architect:	ATI Architects & Engineers, Danville, CA	Plant Job No.:	8726
Engineer:	ATI Architects & Engineers, Danville, CA		
Supplier:	Wood Tech Services, Inc., Eugene, OR		

PROJECT SPECIFICATIONS

Bureau Grade:	WCLIB Rules #17		
Standard Specifications:	ANSI/AITC A190 1 Title 24 Part 2 2312A 6	Adhesive:	Exterior ASTM D-2559-90
Grade Combinations:		Appearance:	Industrial
Simple Beam:	Not Applicable	Coating:	1-Coat All Surfaces
Continuous / Cantilever:	Not Applicable	Wrap:	Bundle wrap
Truss Member / Column:	24F-V8	Moisture Content:	7-12%
End Joint:	Finger	Specifications:	DSA Approved
Separate Adjacent Laminations:	6" per drawing	Special:	---

LUMBER CERTIFICATION

Lumber Grade Mark: APA-EWS
Specie: Douglas Fir / Larch

GLUING: See Page 2 - Report of Inspection

FINISH: Accepted beams marked with FPI Stamp.

QUANTITY 2 Glulams See log.

AFFIDAVIT OF INSPECTION

The fabrication and materials used in the structural members as covered by this Certificate were continuously inspected in accordance with Title 24, Part 2, California Building Code Section 2303.1.3 and 1704A6.2, the project specifications, and the approved shop drawings as follows:

Structural Drawings by: ATI Architects & Engineers, Danville, CA

Shop Print: 8726 by: Wood Tech Services, Inc., Eugene, OR

Approved by: ATI Architects & Engineers, Danville, CA

Title 24 Part 2, California Building Code, 2303.1.3 / 1704A6.2 2007 Edition

Signed: _____

Authorized Inspector for Forest Products Inspection George Neuman DSA Cert #4831

This Certificate refers only to the form and condition of the material at time of inspection. FPI certifies, under penalty of perjury, that Glulam beams covered by this certification were continuously inspected and found in accordance with plans, specifications, and review of quality control records and tests. All acceptable beams are identified by the FPI mark. This Certificate covers only the material and test results shown and is not intended to relieve the manufacturer of the responsibility for the quality of his product.

REPORT OF INSPECTION

Manufacturer Job No. 9726

Manufacturer: Western Structures, Eugene, OR

End Joint Adhesive Manufacturer *4-EX-10*

UMBER GRADE COMBINATIONS. AITC 117-2004. S

Base	Card	Index

21	2	11	0.74	x	60	x	11-0	11-0
----	---	----	------	---	----	---	------	------

χ^2 χ^2

[illegible][illegible]

λ λ

	λ	λ
--	-----------	-----------

[illegible]

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100	

Total Product Inspection

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
84

DSA File Number: 1-31

Spacing
6" per drawing

End Joint Adhesive: HEXION Resin: MFLL Resin Lot No.: 509H-904A Additive: N318LY Additive Lot No.: P09G-06055

Face Bond Adhesive: HEXION Resin: TS710J Resin Lot No.: 509I-547I Hardener: FM631A Hardener Lot No.: 509I-314A

NUMBER GRADE COMBINATIONS: A/C 117-2004: NA Simple Beams (SB): NA Continuous / Cantilever Beams (CB): NA Columns: Z4F-V8

SEALER ALL SURFACE END SEAL

Item	Give	Assembly Times	Conforming
------	------	----------------	------------

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

2010.07.17

[illegible]

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

THE UNIVERSITY OF CHICAGO

[illegible]

100

[illegible]

100

[illegible]

Figure 1. The α - β transition of poly(2-vinylpyridine) (PVP) as a function of the β -phase content. The β -phase content was determined by the thermogravimetric analysis (TGA) of the copolymers. The α - β transition temperature ($T_{\alpha\beta}$) was determined by the differential scanning calorimetry (DSC) of the copolymers. The α - β transition temperature ($T_{\alpha\beta}$) was determined by the differential scanning calorimetry (DSC) of the copolymers.

1. The first part of the document is a title page. It contains the title "THE HISTORY OF THE UNITED STATES OF AMERICA" and the author "BY JAMES MADISON".

Figure 1. Schematic diagram of the experimental setup. The subject is seated in a chair and views the screen through a mirror. The screen displays the target (a red dot) and the starting position (a black dot). The subject's hand is positioned at the starting position. The distance between the starting position and the target is 10 cm. The subject is instructed to move the hand to the target as quickly and accurately as possible. The screen is 100 cm high and 100 cm wide. The subject's hand is positioned at the starting position. The distance between the starting position and the target is 10 cm. The subject is instructed to move the hand to the target as quickly and accurately as possible. The screen is 100 cm high and 100 cm wide.

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

2

STONHAM 1500-10, NUBESU, BANGKOK

1071277

Debris

60970edfbc, **5f7092ad**, **f15d3c3f10**, **c0e0ed8bc**, **b08afcd9ba9**



CONSOLIDATED ENGINEERING
LABORATORIES

November 11, 2009

File #1-31
Application #01-110205
LEA #54

Electronic Reporting

**RE: Havens Elementary School
New Classrooms and Administration Building
1800 Oakland Avenue
Piedmont, CA
CEL #10-22955PW**

**Inspection Date: 10/23/09
Location: Shop
Inspector: Forest Products Inspection
Report #011**

GLUE LAMINATED MEMBER INSPECTION REPORT


On the above date, at our request, Forest Products Inspection performed inspections for the above referenced project.

Inspected glulam beam fabrication. Please refer to the attached for details of inspections performed.

REVIEWING ENGINEER: CHRIS N. KAVALARIS, R.C.E.

cc: Division of State Architect
ATI (E)
MCS, Inc. (E)

PUSDc/o Vila Construction (E)
Piedmont Unified School District (E)
Webcor (E)



Enclosures (2)

All reports are submitted as the confidential property of clients. Publication of statements, conclusions or extracts is reserved pending our written approval.



FOREST PRODUCTS INSPECTION INC.

9739 Soda Bay Road, Kelseyville, CA 95451

Phone (707) 277-7778 Fax (707) 277-7779

Email fpiwood@mchsi.com

CERTIFICATE OF CONTINUOUS INSPECTION OF GLUE LAMINATED MEMBERS

Date:	10/23/2009	Job Code:	20090213
Project:	Havens Elementary School, Piedmont, CA	DSA Application No.:	01-110205
Representative:	Consolidated Engineering Laboratories, Inc., San Ramon, CA	DSA File No.:	1 - 31
Manufacturer:	Calvert Company, Vancouver, WA	Representative No.:	10-22955PW
Architect:	ATI Architects & Engineers, Danville, CA	Plant Job No.:	09-1624
Engineer:	ATI Architects & Engineers, Danville, CA		
Supplier:	Wood Tech Services, Inc., Eugene, OR		

PROJECT SPECIFICATIONS

Bureau Grade:	WCLIB Rules #17		
Standard Specifications:	ANSI/AITC A190.1 Title 24 Part 2 2312A.6	Adhesive:	Exterior ASTM D-2559-90
Grade Combinations:		Appearance:	Industrial
Simple Beam:	24F-V4	Coating:	1-Coat
Continuous / Cantilever:	24F-V8	Wrap:	Bundle wrap
Truss Member / Column:	Not Applicable	Moisture Content:	7-16%
End Joint: Finger	Specifications: DSA Approved	Special:	---
Separate Adjacent Laminations:	6" per drawing		

LUMBER CERTIFICATION

Lumber Grade Mark:	WCLIB	GLUING:	See Page 2 - Report of Inspection
Species:	Douglas Fir / Larch	FINISH:	Accepted beams marked with FPI Stamp.
		QUANTITY	19 Glulams See log:

AFFIDAVIT OF INSPECTION

The fabrication and materials used in the structural members as covered by this Certificate were continuously inspected in accordance with Title 24, Part 2, California Building Code Section 2316A.2 and 2337A.1, the project specifications, and the approved shop drawings as follows:

Structural Drawings by: ATI Architects & Engineers, Danville, CA

Shop Print: 09-1624 by: Wood Tech Services, Inc., Eugene, OR

Approved by: ATI Architects & Engineers, Danville, CA

Title 24 Part 2, California Building Code, 2316A.2 / 2337A.1 2001 Edition

Signed

Authorized Inspector for Forest Products Inspection Larry Nelson, DSA Cert # 4820

This Certificate refers only to the form and condition of the material at time of inspection. FPI certifies, under penalty of perjury, that Glulam beams covered by this certification were continuously inspected and found in accordance with plans, specifications, and review of quality control records and tests. All acceptable beams are identified by the FPI mark. This Certificate covers only the material and test results shown and is not intended to relieve the manufacturer of the responsibility for the quality of his product.

Forest Products Inspection

FPI Job No.: 20099213

Manufacturer Job No. 09-1624

REPORT OF INSPECTION

Date: 10-15-09

Page: 2 of: 2

Project Name: Havens Elementary School, Piedmont, CA

DSA Application Number: 01-110205

Manufacturer: Calvert Company, Vancouver, WA

DSA File Number: 1-31

ADHESIVE: Exterior X ASTM D-2559-90

Spacing: 6" per drawing

End Joint Adhesive: Manufacturer Arclin

Type: Finger

END JOINTS: Resin Lot No. 4001-2

Additive: 5830 S Additive Lot No.: 11-901328

Face Bond Adhesive: Manufacturer Arclin

Resin Lot No. 4001-2

Hardener: 5830 S Hardener Lot No.: 11-901328

LUMBER GRADE COMBINATIONS: AITC 117-2004: Simple Beams (SB): 24FV4

Continuous / Cantilever Beams (CB): 24FV8 Columns: —

APPEARANCE: Industrial

WRAPPING: Load

SEALER: One Coat END SEAL: yes

Beam Mark	Qty	Clamp Up No	Beam Cross Section	Beam Type	Center Radius	No. of Lams	Lumber		Work Room		Glue B / MSF	Assembly Times			Conforming		Manufacture Inspection Dates	
							MC %	Temp	Temp	Hum %		Start	Clamp	Total	Time	Finish	Prep	Glue
AB1	1	1	5 1/8" x 24" x 35'	SB	6"	16	8-11	64	60	55	80	710	730	810	OK	OK	19/15	10/19
AB6	1	1	5 1/8" x 22 1/2" x 24'	SB	5 1/8"	15	8-11	64	60	55	80	710	730	810	OK	OK	19/15	10/19
AB2	1	1	5 1/8" x 22 1/2" x 6'	SB	6"	15	8-11	64	60	55	80	710	730	810	OK	OK	19/15	10/19
AB4	1	1	5 1/8" x 22 1/2" x 15'	SB	35"	15	8-11	64	60	55	80	710	730	810	OK	OK	19/15	10/19
AB3	1	1	5 1/8" x 22 1/2" x 24'	SB	5 1/8"	15	8-11	64	60	55	80	710	730	810	OK	OK	19/15	10/19
AB7	1	2	5 1/8" x 22 1/2" x 24'	SB	5 1/8"	15	7-12	64	62	54	80	830	910	950	OK	OK	19/15	10/19
AB1	1	2	5 1/8" x 22 1/2" x 10'	SB	6"	15	7-12	64	62	54	80	830	910	950	OK	OK	19/15	10/19
AB5	1	2	5 1/8" x 22 1/2" x 11'	SB	6"	15	7-12	64	62	54	80	830	910	950	OK	OK	19/15	10/19
AB4	1	2	5 1/8" x 15" x 15'	SB	6"	10	7-12	64	62	54	60	830	910	950	OK	OK	19/15	10/19
AB5	1	3	6 3/4" x 21" x 39' 6"	CB	1	14	8-11	65	62	54	80	1000	1025	1100	OK	OK	19/15	10/19
AB2	3	3	6 3/4" x 21" x 28'	SB	1	14	8-11	65	62	54	80	1000	1025	1100	OK	OK	19/15	10/19
AB3	1	3	6 3/4" x 21" x 7'	SB	15	14	8-11	65	62	54	80	1000	1025	1100	OK	OK	19/15	10/19
AB6	1	3	6 3/4" x 21" x 40'	CB	1	14	8-11	65	62	54	80	1000	1025	1100	OK	OK	19/15	10/19
AB1	1	3	6 3/4" x 21" x 29'	SB	1	14	8-11	65	62	54	80	1000	1025	1100	OK	OK	19/15	10/19
AB1	1	7	8 3/4" x 25 1/2" x 32'	SB	1	17	7-12	65	62	54	80	210	230	300	OK	OK	19/15	10/19
C1	2	7	8 3/4" x 6" x 11'	CB	6"	4	7-12	65	62	54	80	210	230	300	OK	OK	19/15	10/19

Forest Products Inspection

9739 Soda Bay Road, Kelseyville, CA 95451

(707) 277-7778 FAX (707) 277-7779

Signed:

Larry O'Melara
Authorized Inspector for Forest Products Inspection



State of California
DEPARTMENT OF GENERAL SERVICES
DIVISION OF THE STATE ARCHITECT
 1515 Clay Street, Suite 1201, Oakland, California 94612
 Ph. (510) 622-3101, Fax (510) 622-3140

www.dsa.dgs.ca.gov

Addendum, Change Order,
 Drawing, Deferred Approval
 Worksheet and Transmittal Memo

ATI

NOV 15 2010

RECEIVED

☒ New ☐ Resubmittal Date Sent: File # 1-31 Appl. # 01-110205 YS

Job

Havens Elementary School

Addendum Number	Deferred Submittal	Preliminary Change Order	Change Order Number	Other
			8	

List of Material Received:	A. Master Copy	
	1	
	1	of Sheets(s) Numbers(s)
	D. Prints(s) each	of Sheets(s) Numbers(s)
	E.	
F.		

List of Material Approved:

A+B

List of Material

To: ☐ Architect ☐ Structural Engineer

ATI ARCHITECTS

Address: 3860 Blackhawk Road
 Danville, CA. 94526

To	From
Co.	No. of Pages
Fax No.	Phone No.

☒ Sent

☐ Handed

☐ Faxed

Item

Copies

A
one

11-9-10

KJ

Remaining Requirements:

☒ None

☐ Corrections Required ☐ Change Order Required

If Corrections are required, please submit the following:

- 1) Intact marked up check set.
- 2) This transmittal memo.
- 3) Two corrected copies of submittal.
- 4) Calculations and other back-up information.
- 5) Drawings bearing preliminary approval stamps to avoid re-review whenever possible.

Remarks:

Notes for

☒ Please make file copy of: *1- B*

☐ Other:

Clerical Use

☐ Extend Plans and specs approval to cover:

Only:

☐ Revised Plans and Specs.

☐ Additional: Plans and Specs. Scope Increase:

Type of Approval:

Checked by

ACS

☒ Not Required

FLS

☒ Not Required


SSS

☐ Not Required

Approved by

Date

75
11/8/10



Change Order No. 8

Distribution To:

School District: 1
 ATIA & E: 1
 Contractor: 1
 D.S.A.: 2

Project: Piedmont Unified School District 760 Magnolia Piedmont, CA 94611 (510) 594-2608	Change Order Imitation Date: 9/27/10 D.S.A File No.: 1-31 D.S.A Application No.: 01-110205 ATI Project No.: P7605
---	--

Architect	Contractor
ATI Architects and Engineers 3860 Blackhawk Road Danville, CA 94506 (925) 648-8800	Webcor Builders 207 King Street, 300 San Francisco, CA 94404 415-349-2727

You are hereby authorized to make the following changes to the project. Execution of this change order represents full and final costs of all direct, indirect, and delay costs for the scope of services identified hereon unless noted otherwise.

Change Order No. 8

Item No. 01:	Changes to upper footing foundation at Admin Building
ATI Reference:	ASI #015
Contractor Reference:	PCO #00072
Site:	Havens Elementary
Reason:	Change for 90-deg footing to stepped footing
Requested by:	Architect
Time Extension:	0
Amount: \$ 35,259.00	

3860 Blackhawk Road
 Danville, CA 94526
 T: 925 - 648 - 8800
 F: 925 - 648 - 8811


www.atiae.com

A History of Innovation

Item No. 02:	Utility and Footing Conflicts at 1 & 2 Story Buildings	
ATI Reference:		
Contractor Reference:	PCO #00135	
Site:	Havens Elementary	
Reason:	During excavation of footings several utilities were found to be in conflict with footings. Utilities needed to be relocated. ↙	
Requested by:	Contractor	
Time Extension:	0	
		Amount: \$ 14,528.00

A History of Innovation

Not valid until signed by the School District, Contractor and ATI Architects and Engineers.



		Amount
	Original Contract Sum	\$ 20,500,000.00
	Net Change by previously authorized Change Orders:	\$ 896,562.00
	Contract Sum prior to this Change Order:	\$ 21,396,562.00
	This Change Order Amount Authorized:	\$ 49,787.00
	New Contract Sum Including This Change Order:	\$ 21,446,349.00

Contract Time will be changed by the following: 0 days

Approval Recommended:
ATI Architects and Engineers
3860 Blackhawk Road
Danville, CA 94526

District Approval:
Piedmont Unified School District
760 Magnolia
Piedmont, CA 94611

By: _____
Carl Groch Date
Title: Architect

By: _____
Michael Brady Date
Title: Asst. Superintendent

Accepted:
Webcor Builders
951 Mariners Island Boulevard, Suite 700
San Mateo, CA 94404

By: _____
Spencer Reiner Date
Title: Project Manager

SEE ATTACHED SIGNATURES PAGES

A History of Innovation



OWNER CHANGE ORDER NO. 008

Prime Contract No.: 10136.00

Prime Contract Date:

10136.00 - Havens Elementary School Campus Rebuild
207 King Street 300
San Francisco, CA 94107
Phone: 415-978-1000

To: Webcor Construction LP
951 Mariners Island Boulevard Suite 700
San Mateo, CA 94404
Phone: 349-2727

OCO Date: 12-Aug-2010


The Prime Contract is hereby revised by the following item:

OCO #08 - Final Negotiation / COR's #072 & #135

PCI No.	Description	Amount
00072	ASI 15 - Upper Admin Foundation Change	\$35,259.00
00135	Utility and Footing Conflicts - SE, SW of 2-Story & 1-story	\$14,528.00

Total: \$49,787.00

Original Contract Value	\$20,500,000.00
Sum of change of prior Owner Change Orders	\$896,562.00
The Contract value prior to this Owner Change Order	\$21,396,562.00
The Contract Value will be changed by this Owner Change Order in the amount of	\$49,787.00
The new Contract value including this Owner Change Order will be	\$21,446,349.00
The Contract duration will be changed by	
The revised Substantial Completion date as of this Owner Change Order is	05-Aug-2010



A circular professional engineer seal for the State of California. The outer ring contains the text "REGISTERED PROFESSIONAL ENGINEER" at the top and "STATE OF CALIFORNIA" at the bottom, separated by two stars. The center of the seal contains the name "ARUN SANKAR" in a stylized font, the license number "No. S2839", and the expiration date "Exp. 12/31/09". Below the expiration date, the word "STRUCTURAL" is written in a smaller font.

www.alib.com

ASI NO.: 015


REFERENCE:

DESCRIPTION: Clarifications for footings


Sheet#	Sketch #	Clarification
S1.2	Item (1) through (3): SKS-1 and 2; Item (4): SKS-5	(1) Clarified locations where footing is stepped by calling out Detail B/S0.2 on S1.2. (2) Clarified footing widths on S1.2 which are dimensioned in retaining wall details. (3) Clarified footing below ramp on Gridline 9. Referenced a detail on Sheet S8.1. (4) Denoted footing F2.5/3.5 on plan at Grid B-9.5.
11/S5.1	SKS-3	Clarified footing dimension for F2.5/3.5. It is located at Grid B-9.5.
1/S5.2	SKS-4	Clarified footing below Gridline 9 at ramp.
12/S8.1	SKS-6	Clarified ramp construction with Detail 12/S8.1.

APPROVED
DIV. OF THE STATE ARCHITECT

AC F/LS SS 75
APPL. NO. 91-110205 ATE 9/15/79



Change Order No. 4



Distribution To:
 School District: 1
 ATIA & E: 1
 Contractor: 1
 D.S.A.: 2

Project: Piedmont Unified School District 760 Magnolia Piedmont, CA 94611 (510) 594-2608	Change Order Imitation Date: 6/24/10 D.S.A File No.: 1-31 D.S.A Application No.: 01-110205 ATI Project No.: P7605
---	--

Architect	Contractor
ATI Architects and Engineers 3860 Blackhawk Road Danville, CA 94506 (925) 648-8800	Webcor Builders 207 King Street, 300 San Francisco, CA 94404 415-349-2727

You are hereby authorized to make the following changes to the project. Execution of this change order represents full and final costs of all direct, indirect, and delay costs for the scope of services identified hereon unless noted otherwise.

Change Order No. 4

Item No. 01:	Board/Batten Ceiling - Remainder
ATI Reference:	
Contractor Reference:	PCO #00067B
Site:	Havens Elementary
Reason:	Remainder of the scope beyond the original pricing
Requested by:	Owner
Time Extension:	0
Amount: \$ 2,478.00	

Item No. 02:	2 nd Portion – Piedmont's Dad's Fund Allocation
ATI Reference:	
Contractor Reference:	PCO #00090B
Site:	Havens Elementary
Reason:	Revisions to terra sill ls, tiles in restrooms, paint exterior window sills, relocate lights at 1-story arcade, black vinyl fence, paint gutters
Requested by:	Owner
Time Extension:	0
Amount: \$ 37,674.00	

3860 Blackhawk Road
 Danville, CA 94526
 T: 925 - 648 - 8800
 F: 925 - 648 - 8811

www.atiae.com

A History of Innovation

Not valid until signed by the School District, Contractor and ATI Architects and Engineers.

			Amount
	Original Contract Sum	\$	20,500,000.00
	Net Change by previously authorized Change Orders:	\$	592,183.00
	Contract Sum prior to this Change Order:	\$	21,092,183.00
	This Change Order Amount Authorized:	\$	40,152.00
	New Contract Sum Including This Change Order:	\$	21,132,335.00

Contract Time will be changed by the following: 0 days

Approval Recommended:
ATI Architects and Engineers
3860 Blackhawk Road
Danville, CA 94526

By: Carl Groch 8.12.10
Carl Groch Date
Title: Architect

District Approval:
Piedmont Unified School District
760 Magnolia
Piedmont, CA 94611

By: _____
Michael Brady Date
Title: Asst. Superintendent

SEP - 1 2010

Accepted:
Webcor Builders
951 Mariners Island Boulevard, Suite 700
San Mateo, CA 94404

By: _____
Spencer Reiner Date
Title: Project Manager

SEE ATTACHED SIGNATURES PAGES

A History of Innovation



OWNER CHANGE ORDER NO. 004

Prime Contract No.: 10136.00
Prime Contract Date:

10136.00 - Havens Elementary School Campus Rebuild
207 King Street 300
San Francisco, CA 94107
Phone: 415-978-1000

To: Webcor Construction LP
951 Mariners Island Boulevard Suite 700
San Mateo, CA 94404
Phone: 349-2727

OCO Date: 29-Mar-2010

The Prime Contract is hereby revised by the following item:

Piedmont Dad's Group Items (Beyond OCO #02)

PCI No.	Description	Amount
00067B	Board / Batten Ceiling - Remainder	\$2,478.00
00090B	2nd Portion - Piedmont Dad's Fund Allocation	\$37,674.00


Total: \$40,152.00

Original Contract Value	\$20,500,000.00
Sum of change of prior Owner Change Orders	\$592,183.00
The Contract value prior to this Owner Change Order	\$21,092,183.00
The Contract Value will be changed by this Owner Change Order in the amount of	\$40,152.00
The new Contract value including this Owner Change Order will be	\$21,132,335.00
The Contract duration will be changed by	
The revised Substantial Completion date as of this Owner Change Order is	05-Aug-2010

ARCHITECT

ATI Architect Engineers
3860 Blackhawk Rd.
Danville, CA 94506

By: CARL GROCH
Signature: [Signature]
Date: 6.24.10



CONTRACTOR

Webcor Construction LP
951 Mariners Island Boulevard Suite
700
San Mateo, CA 94404

By: SPENCER REINER
Signature: [Signature]
Date: 6/24/10

OWNER

Piedmont Unified School District
760 Magnolia
Piedmont, CA 94611

By: [Signature]
Signature: MICHAEL GRADY
Date: 7/1/10

[Signature]
Pete Palmer
CM USD VCC
6/24/10

APPROVED
DIV OF THE STATE ARCHITECT
AC [Signature] F/L [Signature] SS [Signature]
APPL NO. 1022 DATE 9/16/10

Department of
General Services
 BUILDING GREEN-BUYING GREEN-WORKING GREEN

Project's Deferred Approval

Office ID:01

Application #:110205

File #:1-31

Project Name:Haven Elementary School

Please select the deferred approval which you want to review

	Item Name	Received
<input checked="" type="radio"/>	Automatic Fire Sprinkler Systems	09/09/2009
<input type="radio"/>	Elevator Guide Rails and Support Bracket Anchorage	02/22/2010
<input type="radio"/>	Basketball Backstops	08/24/2009

Item Name:Automatic Fire Sprinkler Systems

Special Assigned to SSS BFANG for review. ss to fls 9/16/09. FLS (GB) reviewed w/comments; routed to SSS 9/24/09.ss to arch 10/7/09. Routed to SSS WFANG for review. FLS (GB) reviewed w/comments; routed to SSS 11/25/09. ss to arch 11/30/09. ss to fls 12/23/09. FLS reviewed;

Notes:routed to SSS 1/27/10. ss disapproved & sent to arch. 1/27/10. Resubmitted on 02/11/2010 routed to SSS WFang for further review on 02/11/2010. (2) dwg sets are missing in the re-submittal, return to arch 2/17/10. Resubmitted on 02/18/2010 routed to SSS WFang for further review on 02/18/2010. ss to arch 3/4/10.

Received Date:9/9/2009

Approval Date:

Canceled Date:

	Access Review	Fire & Life Safety Review	Structural Safety Review
Status:	Not Required	Approved	Approved
Date:		1/27/2010	3/4/2010

[Conditions of Use](#) | [Privacy Policy](#)
 Copyright © 2007 State of California



STATE OF CALIFORNIA • DEPARTMENT OF GENERAL SERVICES
DIVISION OF THE STATE ARCHITECT

FORM



DSA-293

Rev. 08/07/06

RECEIVED

Geotechnical Verified Report (GVR)

Note: This form must be submitted by the Responsible Geotechnical Engineer within 14 days of the conclusion of the testing / inspection program, or when work has stopped for more than one month, or if the services of the Geotechnical Engineer have been terminated for any reason.

<p>A. Re: Interim Housing</p> <p>Project Name <u>Havens Elementary School</u></p> <p>School Name <u>Piedmont Unified School District</u></p> <p>School Dist. <u>760 Magnolia Avenue</u></p> <p>Address <u>Piedmont, CA 94611-4088</u></p> <p><u>Constance Hubbard, Superintendent</u></p> <p>Attention</p>	<p>1-31</p> <p>DSA File # <u>01-110621</u></p> <p>DSA App. #</p> <p><input checked="" type="radio"/> Final-Work 100% Complete</p> <p><input type="radio"/> In-Progress: _____ % Complete</p> <p><input type="radio"/> Terminating: _____ % Complete</p>
<p>B. It is my professional opinion that all of the engineered fill tests and inspections required by the Division of the State Architect (DSA) approved documents for the project identified in Section A were performed. Any tests of which I am aware that were not performed are listed on an attachment to this report.</p> <p>I am of the professional opinion that the tests were performed in accordance with the requirements of the DSA approved documents.</p>	
<p>C. All reports were sent to all entities as required by code.</p>	
<p>D. Qualified personnel under my direct supervision conducted all testing and inspection services.</p>	
<p>E. The results of all tests and inspections indicate that the materials tested comply with the requirements of the DSA approved documents.</p>	
<p>F. I declare under penalty of perjury that this report was prepared under my direct supervision, I know the contents thereof, and that all of the statements are true and correct.</p> <div style="display: flex; justify-content: space-between; align-items: flex-start;"> <div style="width: 45%;"> <p>Signed </p> <p>GEOTECHNICAL ENGINEER</p> <p>Print Name: <u>Eric J. Swenson</u></p> <p>Lab Name: <u>Consolidated Engineering Laboratories</u></p> <p>Address: <u>2001 Crow Canyon Road, Suite 100</u></p> <p>City: <u>San Ramon</u> State: <u>CA</u> Zip: <u>94583-5387</u></p> </div> <div style="width: 30%; text-align: center;">  <p>Affix Seal Here</p> </div> <div style="width: 20%; text-align: right;"> <p><u>01/27/10</u></p> <p>Date</p> </div> </div> <p>DSA /LEA # <u>54</u></p>	

cc: Project Architect
 Structural Engineer
 Project Inspector
 DSA Regional office

See other side for instructions

	< WebShip > > > > > 800-322-5555 www.gso.com
---	---

Ship From: DONNA FOSTER ATI ARCHITECTS AND ENGINEERS 3860 BLACKHAWK ROAD DANVILLE, CA 94506 Ship To: YUNG SU DIVISION OF THE STATE ARCHITECT 1515 CLAY STREET SUITE 1201 OAKLAND, CA 94612 COD: \$0.00 Reference: P7605 - CLOSE OUT DOCUMENTS Delivery Instructions: Signature Type: SIGNATURE REQUIRED	Tracking #: 515624026 	PDS
	OAK	
	OAKLAND	
	D94612A  87384619	
Print Date : 12/23/10 09:49 AM		

Package 1 of 1

Send Label To Printer	<input checked="" type="checkbox"/> Print All	Edit Shipment	Finish
-----------------------	---	---------------	--------

LABEL INSTRUCTIONS:

Do not copy or reprint this label for additional shipments - each package must have a unique barcode.

STEP 1 - Use the "Send Label to Printer" button on this page to print the shipping label on a laser or inkjet printer.

STEP 2 - Fold this page in half.

STEP 3 - Securely attach this label to your package, do not cover the barcode.

STEP 4 - Request an on-call pickup for your package, if you do not have scheduled daily pickup service or Drop-off your package at the nearest GSO drop box. Locate nearest GSO dropbox locations using this link.

ADDITIONAL OPTIONS:

Send Label Via Email	Create Return Label
----------------------	---------------------

TERMS AND CONDITIONS:

By giving us your shipment to deliver, you agree to all the service terms and conditions described in this section.

Our liability for loss or damage to any package is limited to your actual damages or \$100 whichever is less, unless you pay for and declare a higher authorized value. If you declare a higher value and pay the additional charge, our liability will be the lesser of your declared value or the actual value of your loss or damage. In any event, we will not be liable for any damage, whether direct, incidental, special or consequential, in excess of the declared value of a shipment whether or not we had knowledge that such damage might be incurred including but not limited to loss of income or profit. We will not be liable for your acts or omissions, including but not limited to improper or insufficient packaging, securing, marking or addressing. Also, we will not be liable if you or the recipient violates any of the terms of our agreement. We will not be liable for loss, damage or delay caused by events we cannot control, including but not limited to acts of God, perils of the air, weather conditions, act of public enemies, war, strikes, or civil commotion. The highest declared value for our GSO Priority Letter or GSO Priority Package is \$500. For other shipments the highest declared value is \$10,000 unless your package contains items of "extraordinary value", in which case the highest declared value we allow is \$500. Items of "extraordinary value" include, but are not limited to, artwork, jewelry, furs, precious metals, tickets, negotiable instruments and other items with intrinsic value.

Donna Foster

From: webship@gso.com
Sent: Friday, December 24, 2010 9:33 AM
To: Donna Foster
Subject: GSO Shipment Delivery Notification - 515624026

DELIVERY NOTIFICATION:

Tracking Number: 515624026
Ship Date: 12/23/2010
Ship From: DONNA FOSTER, ATI ARCHITECTS AND ENGINEERS
Ship To: YUNG SU, DIVISION OF THE STATE ARCHITECT
1515 CLAY STREET SUITE 1201
OAKLAND CA 94612
Billing Reference: P7605 - CLOSE OUT DOCUMENT
Delivered At: 12/24/2010 09:28 AM
Signed By: T. Thomas

SENDER COMMENTS:

No sender comments for this shipment

Please use the following link to track the history of this shipment online:
<http://www.gso.com/deliveryinforequest.aspx?trackingnum=515624026>

Please DO NOT REPLY TO THIS MESSAGE. For general inquiries, contact GSO customer service at 1-800-322-5555

Visit us at: <http://www.gso.com>

This email and any files transmitted with it are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you are not the intended recipient of this email, you are notified that disclosing, copying, distributing this message is strictly prohibited. If you have received this email in error, please delete it immediately.

Donna Foster

From: Malig, Reymond [Reymond.Malig@dgs.ca.gov]
Sent: Thursday, March 24, 2011 12:36 PM
To: Donna Foster; A1 Close Out Team
Cc: Rup Chand; Sherman Koo; Tim Steele
Subject: RE: Projects Waiting for Closeout (SA6901, P7605, P7606, A3257, M2632.004)

Hi Donna,

Please provide status of close out (DSA Tracker has been checked)

DSA App No

01-108816 Live Oak ES – submitted 1/12/11 corrected lab reports- 90day ltr sent

01-110205 Havens ES – submitted for close 12/23/10 – District requested status report-Active

01-110621 Havens ES Interim Housing – 90 day expired 9/10 – District requested status report-90day

01-110940 Miramonte Tennis Court Lighting – submitted 11/2/10 – District requested status report-Active

01-110981 Riverview – submitted 12/09/10 – District requested status report-Active

Thank you,

Reymond Malig
Triage/Closing Specialist/ PTII
Division of the State Architect
Oakland Regional Office
Department of General Services
1515 Clay Street, Suite 1201
Oakland, CA 94612
(510) 622-5656 (Tel.)
(510) 622-3073 (Fax)
rmalig@dgs.ca.gov



BUILDING GREEN • BUYING GREEN • WORKING GREEN

From: Donna Foster [<mailto:dfoster@ataie.com>]
Sent: Monday, March 14, 2011 1:23 PM
To: A1 Close Out Team
Cc: Rup Chand; Sherman Koo; Tim Steele
Subject: Projects Waiting for Closeout (SA6901, P7605, P7606, A3257, M2632.004)

Please provide status of close out (DSA Tracker has been checked)

DSA App No

01-108816 Live Oak ES – submitted 1/12/11 corrected lab reports

01-110205 Havens ES – submitted for close 12/23/10 – District requested status report

01-110621 Havens ES Interim Housing – 90 day expired 9/10 – District requested status report

01-110940 Miramonte Tennis Court Lighting – submitted 11/2/10 – District requested status report

01-110981 Riverview – submitted 12/09/10 – District requested status report